SAMRUDH
Architects and Interior Designers

Name of Work : Improvements to Roads and Drains around Ramachandrapura, Kuvempunagara, Vaishnavi Layout, Srinidhi Layout and Sai Garden in Ward No.11 Kuvempunagara, BBMP, Bangalore.

Name of Client	:	**Executive Engineer,** Project Division, Yelahanka Zone, BBMP, Bangalore.
Contractor/Agency	:	**Sri. Acthuth Murthy,** Contractor, Bangalore.
Total Cost	:	Rs. 35.01 Lakhs
Date of Inspection	:	22.11.2019
Status of Bill	:	2nd and Final bill
In the Presence of	:	(a) **Assistant Engineer (Ward No.11),** BBMP, Bangalore. M/s Samrudh Architects & Engineers, Bangalore.

PMC Report

Sl.No	Description of the Item		Comments / observations
1	Removing and refixing stone slabs of drains and pointing in CM (1:3)	:	Work done up to the billed quantity and Quality is satisfactory
2	Earthwork excavation by manual means in ordinary soil involving an average horizontal throw upto	:	Work done up to the billed quantity and Quality is satisfactory
3	Providing and laying in position plain cement concrete of mix 1:2:4 with cement @ 240kgs,	:	Work done up to the billed quantity and Quality is satisfactory
4	Providing and constructing precast concrete solid blocks with compressive strength not less	:	Work done up to the billed quantity and Quality is satisfactory
5	Providing granite slabs of selected quality roughly dressed and fixed in cement mortar (1:6)	:	Work done up to the billed quantity and Quality is satisfactory
6	Providing and Fixing pre cast covering Slab made out of CC 1:2:4 with 10cm thick and	:	Work done up to the billed quantity and Quality is satisfactory

#M-32,25TH Main,LICRaoHousing,J.P Nagar 1st Phase,
Po Box 7826,Bengaluru-560078. Mobile:+91 9845167738 Tele Fax 080-41211493
E-mail:klsuguna7@gmail.com .www.ezdihaar.com

7	Excavation for roadwork in all types of soil by mechanical means including cutting and loading to tippers, trimming	:	Work done up to the billed quantity and Quality is satisfactory
8	Dismantling of cement concrete pavement by mechanical means using pneumatic tools, breaking to pieces not exceeding 0.02 cum	:	Work done up to the billed quantity and Quality is satisfactory
9	Construction of granular sub-base Grading-V as Sub-base and drainage layer by providing coarse graded crushed stone aggregates of granite/ trap/basalt	:	Work done up to the billed quantity and Quality is satisfactory
10	Providing and laying in position plain cement concrete of Mix 1:3:6 with OPC @ 220kgs, with 40mm and down size graded granite metal coarse aggregates @0.892cum and fine aggregates	:	Work done up to the billed quantity and Quality is satisfactory

ARCHITECTURAL DESIGN ★ SAMRUDH

#M-32,25TH Main,LICRaoHousing,J.P Nagar 1st Phase,
Po Box 7826,Bengaluru-560078. Mobile:+91 9845167738 Tele Fax 080-41211493
E-mail:klsuguna7@gmail.com .www.ezdihaar.com